

FACILITY SCORECARD

Leroy Elementary School



1451 Leroy Dr., Northglenn, CO
Established in 1962 | 52,332 sq. ft.
Additions: 1966, 1981, 2007

TOTAL REPAIR COST: \$3.9 MILLION*
Last known major repairs over \$250,000: 2007

** Values listed are approximate and are subject to change based on project estimates and additional discovery.*

552
415

CAPACITY
2015 ENROLLMENT

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

OVERALL CONDITION RATING



The facility's systems are quickly approaching or exceeding their life expectancy. Look for more information this fall on how we will address your school's needs.



BUILDING STRUCTURE
Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



BUILDING INTERIORS
Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



EQUIPMENT & FURNISHINGS
Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



BUILDING SYSTEMS
Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



SCHOOL GROUNDS
Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

Now what?



Visit www.adams12.org/FacilityScorecard to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help