

# FACILITY SCORECARD

## Skyview Elementary School



5021 E. 123rd Ave., Thornton, CO  
Established in 1986 | 48,973 sq. ft.

**TOTAL REPAIR COST: \$1.6 MILLION\***  
Last known major repairs over \$250,000: 2006

576  
499

**CAPACITY**  
**2015 ENROLLMENT**

*\* Values listed are approximate and are subject to change based on project estimates and additional discovery.*

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

### OVERALL CONDITION RATING



## MODERATE

The facility needs moderate repairs.  
Look for more information this fall on how we will address your school's needs.



**\$0.2 MILLION  
COST TO REPAIR**

### EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



### BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



**\$0.8 MILLION  
COST TO REPAIR**

### BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



### BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



**\$0.1 MILLION  
COST TO REPAIR**

### SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

## Now what?



Visit [www.adams12.org/FacilityScorecard](http://www.adams12.org/FacilityScorecard) to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help