

# FACILITY SCORECARD

## Cherry Drive Elementary School



11500 Cherry Dr., Thornton, CO  
Established in 1978 | 49,561 sq. ft. (includes mobiles)  
Additions: 1992

**TOTAL REPAIR COST: \$5.0 MILLION\***  
Last known major repairs over \$250,000: 2004

*\* Values listed are approximate and are subject to change based on project estimates and additional discovery.*

576  
387

CAPACITY  
2015 ENROLLMENT

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

### OVERALL CONDITION RATING



The facility is experiencing major systems failure due to an overextended life expectancy. Look for more information this fall on how we will address your school's needs.

  
**\$1.8 MILLION  
COST TO REPAIR**

#### BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.

  
**\$0.6 MILLION  
COST TO REPAIR**

#### BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.

  
**\$0.5 MILLION  
COST TO REPAIR**

#### EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.

  
**\$1.6 MILLION  
COST TO REPAIR**

#### BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.

  
**\$0.5 MILLION  
COST TO REPAIR**

#### SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

## Now what?



Visit [www.adams12.org/FacilityScorecard](http://www.adams12.org/FacilityScorecard) to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help