

FACILITY SCORECARD

Coronado Hills Elementary Schools

8300 Downing Dr., Denver, CO
Established in 2009 | 71,842 sq. ft.



TOTAL REPAIR COST: \$0 MILLION*
Last known major repairs over \$250,000: 2009

** Values listed are approximate and are subject to change based on project estimates and additional discovery.*

576
523

CAPACITY
2015 ENROLLMENT

SYSTEM RATING Good Moderate Poor Critical

OVERALL CONDITION RATING



The facility is in good overall condition, needing only minor repairs.
Look for more information this fall on how we will address your school's needs.



BUILDING STRUCTURE
Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



BUILDING INTERIORS
Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



EQUIPMENT & FURNISHINGS
Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



BUILDING SYSTEMS
Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



SCHOOL GROUNDS
Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

Now what?



Visit www.adams12.org/FacilityScorecard to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help