

# FACILITY SCORECARD

## Bollman Technical Education Center

9451 Washington St., Thornton, CO

Established in 1974 | 69,578 sq. ft. (includes mobiles)

Additions: 1975, 1984, 1991



**TOTAL REPAIR COST: \$4.1 MILLION\***


Last known major repairs over \$250,000: 2005

*\* Values listed are approximate and are subject to change based on project estimates and additional discovery.*

!	900	CAPACITY
	909	2015 ENROLLMENT
	2	MOBILE CLASSROOMS
		Mobiles provide additional space

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

### OVERALL CONDITION RATING



**MODERATE**

The facility needs moderate repairs.  
Look for more information this fall on how we will address your school's needs.



**\$0.6 MILLION COST TO REPAIR**

### EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



**\$0.1 MILLION COST TO REPAIR**

### BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



**\$2.1 MILLION COST TO REPAIR**

### BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



**\$0.5 MILLION COST TO REPAIR**

### BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



**\$0.8 MILLION COST TO REPAIR**

### SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

## Now what?



Visit [www.adams12.org/FacilityScorecard](http://www.adams12.org/FacilityScorecard) to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help