

# FACILITY SCORECARD

## Shadow Ridge Middle School

12551 Holly St., Thornton, CO  
Established in 2003 | 153,301 sq. ft.



**TOTAL REPAIR COST: \$2.3 MILLION\***  
Last known major repairs over \$250,000: 2003

**1,250**  
**1,003**

**CAPACITY**  
**2015 ENROLLMENT**

*\* Values listed are approximate and are subject to change based on project estimates and additional discovery.*

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

### OVERALL CONDITION RATING



The facility is in good overall condition, needing only minor repairs.  
Look for more information this fall on how we will address your school's needs.



### EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



### BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



### BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



### BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



### SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

## Now what?



Visit [www.adams12.org/FacilityScorecard](http://www.adams12.org/FacilityScorecard) to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help