

FACILITY SCORECARD

The Studio School

10604 Grant Dr., Northglenn, CO
Established in 1960 | 41,338 sq. ft.
Additions: 1966, 1981, 2003



TOTAL REPAIR COST: \$3.0 MILLION*
Last known major repairs over \$250,000: 2007

** Values listed are approximate and are subject to change based on project estimates and additional discovery.*

300
282

CAPACITY
2015 ENROLLMENT

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

OVERALL CONDITION RATING



The facility's systems are quickly approaching or exceeding their life expectancy. Look for more information this fall on how we will address your school's needs.



**\$0.8 MILLION
COST TO REPAIR**

EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



**\$0.7 MILLION
COST TO REPAIR**

BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



**\$0.7 MILLION
COST TO REPAIR**

BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



**\$0.5 MILLION
COST TO REPAIR**

BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



**\$0.3 MILLION
COST TO REPAIR**

SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

Now what?



Visit www.adams12.org/FacilityScorecard to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help