

FACILITY SCORECARD

Rocky Mountain Elementary School



3350 W. 99th Ave., Westminster, CO
Established in 1987 | 54,289 sq. ft.



TOTAL REPAIR COST: \$1.9 MILLION*
Last known major repairs over \$250,000: 2012

552
488

CAPACITY
2015 ENROLLMENT

** Values listed are approximate and are subject to change based on project estimates and additional discovery.*

SYSTEM RATING Good Moderate Poor Critical

OVERALL CONDITION RATING



MODERATE

The facility needs moderate repairs.
Look for more information this fall on how we will address your school's needs.



**\$0.1 MILLION
COST TO REPAIR**

EQUIPMENT & FURNISHINGS

Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.



**\$0 MILLION
COST TO REPAIR**

BUILDING STRUCTURE

Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.



**\$1.3 MILLION
COST TO REPAIR**

BUILDING SYSTEMS

Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.



**\$0.1 MILLION
COST TO REPAIR**

BUILDING INTERIORS

Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.



**\$0.4 MILLION
COST TO REPAIR**

SCHOOL GROUNDS

Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

Now what?



Visit www.adams12.org/FacilityScorecard to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help