

FACILITY SCORECARD

Westview Elementary School



1300 Roseanna Dr., Northglenn, CO
Established in 1968 | 56,850 sq. ft.
Additions: 1981, 1991

TOTAL REPAIR COST: \$4.6 MILLION*
Last known major repairs over \$250,000: 2006

** Values listed are approximate and are subject to change based on project estimates and additional discovery.*

576
419

CAPACITY
2015 ENROLLMENT

SYSTEM RATING ● Good ● Moderate ● Poor ● Critical

OVERALL CONDITION RATING



The facility's systems are quickly approaching or exceeding their life expectancy. Look for more information this fall on how we will address your school's needs.

● ○ ○ ○
**\$0.5 MILLION
COST TO REPAIR**

BUILDING STRUCTURE
Includes structural supports both in the basement and above ground such as exterior and interior walls and columns, roofs, exterior doors, exterior windows, frames, ramps, decks, etc.

○ ○ ○ ●
**\$1.3 MILLION
COST TO REPAIR**

BUILDING INTERIORS
Non-structural items inside the building including doors, floors, walls, stairs, ceilings, etc.

○ ○ ○ ●
**\$0.2 MILLION
COST TO REPAIR**

EQUIPMENT & FURNISHINGS
Interior fixtures and equipment for school classrooms, kitchens, libraries and computer networks (including wireless); bleachers; playgrounds, etc.

○ ○ ● ○
**\$2.0 MILLION
COST TO REPAIR**

BUILDING SYSTEMS
Includes heating and cooling, plumbing, electrical, fire protection, elevators, etc.

○ ○ ● ○
**\$0.6 MILLION
COST TO REPAIR**

SCHOOL GROUNDS
Safety and security systems, pavement, sidewalks, playfields, landscaping, site water, site electricity, etc.

Now what?



Visit www.adams12.org/FacilityScorecard to find information on:

- how the ratings are made
- how these scores affect your child
- how to understand our district and state funding challenges
- how we plan on addressing these needs
- how you can help