

## Water Sampling Results

### Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above  
 ND: Non-detect (below detection limit) | PPB: Parts per Billion

**School Name**    **ESC Building**

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	041117.601A.11DF.01	Drinking fountain, hallway 11, north wall	ND	-	-	1
	041117.601A.11DF.02	Drinking fountain, hallway 11, east wall	ND	-	-	1
	041117.601A.18DF.01	Drinking fountain, hallway 18, east wall, right side DF	ND	-	-	1
	041117.601A.18DF.02	Drinking fountain, hallway 18, east wall, left side DF	2	-	-	1
	041117.601A.A153DF.01	Drinking fountain, room AE153, south wall, left side DF	ND	-	-	1
	041117.601A.A153DF.02	Drinking fountain, room AE153, south wall, right side DF	ND	-	-	1
	041117.601A.A171SK.01	Sink, room A171, north wall, left side	0.58	-	-	1
	041117.601A.A171SK.02	Sink, room A171, north wall, bottle fill station	1.3	-	-	1
	041117.601A.A225BSK.01	Sink, room A225B	1	-	-	1
	041117.601A.A331SK.01	Sink, room A331	0.78	-	-	1
	041117.601A.AE170DF.01	Drinking fountain, room AE170, west wall, left side DF	ND	-	-	1
	041117.601A.AE170DF.02	Drinking fountain, room AE170, west wall, right side DF	ND	-	-	1
	041117.601A.AE170SK.01	Sink, room AE170, north wall, left side	0.84	-	-	1
	041117.601A.AE170SK.02	Sink, room AE170, north wall, bottle fill station	0.77	-	-	1
	041117.601A.AMS4SK.01	Sink, room AMS4 (maintenance break room)	0.98	-	-	1
	041117.601A.D131SK.01	Sink, room D131, Blue Sage kitchen	1	-	-	1
	041117.601A.D131SK.02	Sink, room D131, Blue Sage kitchen	4.9	-	-	1
	041117.601A.D131SK.03	Sink, room D131, Blue Sage kitchen	2.4	-	-	1
	041117.601A.D131SK.04	Sink, room D131, Blue Sage kitchen	1.8	-	-	1
	041117.601A.D131SK.05	Sink, room D131, Blue Sage kitchen	3.7	-	-	1
	041117.601A.D131SK.06	Sink, room D131, Blue Sage kitchen	0.94	-	-	1
	041117.601A.D131SK.07	Sink, room D131, Blue Sage kitchen	1.3	-	-	1
	041117.601A.D131SK.08	Sink, room D131, Blue Sage kitchen	3.3	-	-	1
	041117.601A.D131SK.09	Sink, room D131, Blue Sage kitchen	0.5	-	-	1
	041117.601A.H100DF.01	Drinking fountain, hallway H100, west wall, left side	ND	-	-	1
	041117.601A.H100DF.02	Drinking fountain, hallway H100, west wall, bottle fill station	ND	-	-	1
	041117.601A.N07DF.01	Sink, hallway N07, left side DF	0.73	-	-	1
	041117.601A.N07DF.02	Sink, hallway N07, right side DF	0.5	-	-	1
	041117.601A.N174SK.01	Sink, room N174	0.84	-	-	1
	041117.601A.N222SK.01	Sink, room N222	0.63	-	-	1
	041117.601A.N237SK.01	Sink, room N237	1.6	-	-	1
	041117.601A.PSBREAKSK.01	Sink, room PSBREAK (print shop break room)	7	-	-	1
	041117.601A.PSBREAKSK.02	Sink, room PSBREAK, bottle fill station (print shop break room)	2.2	-	-	1
	041117.601A.PSSHOPSK.01	Sink, room PSSHOP (print shop)	3.3	-	-	1
	041117.601A.WARESK.01	Sink, room WARE (warehouse)	1.1	-	-	1
<b>Initial Sample Total</b>						<b>35</b>