

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above
 ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name **Glacier Peak ES**

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	022317.196A.A100SK.01	Sink, room A100	ND	-	-	1
	022317.196A.A101SK.01	Sink, room A101	2.1	-	-	1
	022317.196A.A109SK.01	Sink, room A109	ND	-	-	1
	022317.196A.A115DF.01	Drinking fountain, hallway A115, north wall, west end, right	ND	-	-	1
	022317.196A.A115DF.02	Drinking fountain, hallway A115, north wall, west end, left s	ND	-	-	1
	022317.196A.A115DF.03	Drinking fountain, hallway A115, north wall, east end, right :	ND	-	-	1
	022317.196A.A115DF.04	Drinking fountain, hallway A115, north wall, east end, left si	ND	-	-	1
	022317.196A.A120SK.01	Sink, room A120	ND	-	-	1
	022317.196A.A123SK.01	Sink, room A123, south side	2.2	-	-	1
	022317.196A.A123SK.02	Sink, room A123, SE corner	0.6	-	-	1
	022317.196A.A123SK.03	Sink, room A123, east side	2.5	-	-	1
	022317.196A.A129DF.01	Drinking fountain, room A129, right DF	ND	-	-	1
	022317.196A.A129DF.02	Drinking fountain, room A129, left DF	ND	-	-	1
	022317.196A.A134SK.01	Sink, room A134, gym office	20	Taken offline	-	1
	022317.196A.B103.1DF.01	Drinking fountain, room B103.1, attached to sink	ND	-	-	1
	022317.196A.B103.1SK.01	Sink, room B103.1	0.53	-	-	1
	022317.196A.B104.1DF.01	Drinking fountain, room B104.1, attached to sink	ND	-	-	1
	022317.196A.B104.1SK.01	Sink, room B104.1	0.73	-	-	1
	022317.196A.B104DF.01	Drinking fountain, room B104, attached to sink	ND	-	-	1
	022317.196A.B104SK.01	Sink, room B104	ND	-	-	1
	022317.196A.B107.1DF.01	Drinking fountain, room B107.1, attached to sink	ND	-	-	1
	022317.196A.B107.1SK.01	Sink, room B107.1	ND	-	-	1
	022317.196A.B108.1DF.01	Drinking fountain, room B108.1, attached to sink	ND	-	-	1
	022317.196A.B108.1SK.01	Sink, room B108.1	ND	-	-	1
	022317.196A.B111.1DF.01	Drinking fountain, room B111.1, attached to sink	ND	-	-	1
	022317.196A.B111.1SK.01	Sink, room B111.1	0.79	-	-	1
	022317.196A.B112.1DF.01	Drinking fountain, room B112.1, attached to sink	ND	-	-	1
	022317.196A.B112.1SK.01	Sink, room B112.1	ND	-	-	1
	022317.196A.C103.1DF.01	Drinking fountain, room C103.1, attached to sink	ND	-	-	1
	022317.196A.C103.1SK.01	Sink, room C103.1	1	-	-	1
	022317.196A.C104.1DF.01	Drinking fountain, room C104.1, attached to sink	ND	-	-	1
	022317.196A.C104.1SK.01	Sink, room C104.1	ND	-	-	1
	022317.196A.C107.1DF.01	Drinking fountain, room C107.1, attached to sink	ND	-	-	1
	022317.196A.C107.1SK.01	Sink, room C107.1	0.58	-	-	1
	022317.196A.C108.1DF.01	Drinking fountain, room C108.1, attached to sink	ND	-	-	1
	022317.196A.C108.1SK.01	Sink, room C108.1	0.93	-	-	1
	022317.196A.C111.1DF.01	Drinking fountain, room C111.1, attached to sink	ND	-	-	1
	022317.196A.C111.1SK.01	Sink, room C111.1	0.55	-	-	1
	022317.196A.C112.1DF.01	Drinking fountain, room C112.1, attached to sink	ND	-	-	1
	022317.196A.C112.1SK.01	Sink, room C112.1	0.57	-	-	1
	022317.196A.C115.1DF.01	Drinking fountain, room C115.1, attached to sink	ND	-	-	1
	022317.196A.C115.1SK.01	Sink, room C115.1	0.7	-	-	1
Initial Sample Total						42
Retest Sample - 1	041117.196A.A134SK.01	Sink, room A134, gym office	11	Back in service	4/27/2017	1
Retest Sample - 1 Total						1