

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Mountain Range HS

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	042917.380A.A108DF.01	Drinking fountain, hallway A108, north wall, left side DF	ND	-	-	1
	042917.380A.A108DF.02	Drinking fountain, hallway A108, north wall, right side DF	ND	-	-	1
	042917.380A.A110DF.01	Drinking fountain, hallway A110, north wall, left side DF	ND	-	-	1
	042917.380A.A110DF.02	Drinking fountain, hallway A110, north wall, right side DF	ND	-	-	1
	042917.380A.A208DF.01	Drinking fountain, hallway A208, north wall, left side DF	ND	-	-	1
	042917.380A.A208DF.02	Drinking fountain, hallway A208, north wall, right side DF	ND	-	-	1
	042917.380A.B113SK.01	Sink, room B113	0.68	-	-	1
	042917.380A.B208DF.01	Drinking fountain, hallway B208, north wall, left side DF	ND	-	-	1
	042917.380A.B208DF.02	Drinking fountain, hallway B208, north wall, right side DF	ND	-	-	1
	042917.380A.C114DF.01	Drinking fountain, hallway C114, south wall, far left side DF	ND	-	-	1
	042917.380A.C114DF.02	Drinking fountain, hallway C114, south wall, right of DF.01	ND	-	-	1
	042917.380A.C114DF.03	Drinking fountain, hallway C114, south wall, left of DF.04	ND	-	-	1
	042917.380A.C114DF.04	Drinking fountain, hallway C114, south wall, far right side D	ND	-	-	1
	042917.380A.C128DF.01	Drinking fountain, hallway C128, north wall, far left side DF	ND	-	-	1
	042917.380A.C128DF.02	Drinking fountain, hallway C128, north wall, right of DF.01	ND	-	-	1
	042917.380A.C128DF.03	Drinking fountain, hallway C128, north wall, left of DF.04	ND	-	-	1
	042917.380A.C128DF.04	Drinking fountain, hallway C128, north wall, far right side D	ND	-	-	1
	042917.380A.C210DF.01	Drinking fountain, hallway C210, south wall, far right side D	ND	-	-	1
	042917.380A.C210DF.02	Drinking fountain, hallway C210, south wall, left of DF.01	ND	-	-	1
	042917.380A.C210DF.03	Drinking fountain, hallway C210, south wall, right of DF.04	ND	-	-	1
	042917.380A.C210DF.04	Drinking fountain, hallway C210, south wall, far left side DF	ND	-	-	1
	042917.380A.C218DF.01	Drinking fountain, hallway C218, north wall, far left side DF	ND	-	-	1
	042917.380A.C218DF.02	Drinking fountain, hallway C218, north wall, right of DF.01	ND	-	-	1
	042917.380A.C218DF.03	Drinking fountain, hallway C218, north wall, left of DF.04	ND	-	-	1
	042917.380A.C218DF.04	Drinking fountain, hallway C218, north wall, far right side D	ND	-	-	1
	042917.380A.C225SK.01	Sink, room C225	1.6	-	-	1
	042917.380A.C242SK.01	Sink, room C242	0.62	-	-	1
	042917.380A.D103SK.01	Sink, room D103	ND	-	-	1
	042917.380A.D117DF.01	Drinking fountain, hallway D117, north wall, left side DF	ND	-	-	1
	042917.380A.D117DF.02	Drinking fountain, hallway D117, north wall, right side DF	ND	-	-	1
	042917.380A.D117DF.03	Drinking fountain, hallway D117, north wall, bottle fill stati	ND	-	-	1
	042917.380A.D118SK.01	Sink, room D118	ND	-	-	1
	042917.380A.D123SK.01	Sink, room D123, west wall, right side SK	1	-	-	1
	042917.380A.D123SK.02	Sink, room D123, west wall, left side SK	ND	-	-	1
	042917.380A.D127SK.01	Sink, room D127, west wall, right side SK	0.84	-	-	1
	042917.380A.D127SK.02	Sink, room D127, west wall, left side SK	0.54	-	-	1
	042917.380A.D127SK.03	Sink, room D127, east wall, right side SK	0.71	-	-	1
	042917.380A.D127SK.04	Sink, room D127, east wall, left side SK	2.5	-	-	1
	042917.380A.D134SK.01	Sink, hallway D134	ND	-	-	1
	042917.380A.D142SK.01	Sink, room D142	ND	-	-	1
	042917.380A.D149SK.01	Sink, room D149	ND	-	-	1
	042917.380A.D205ASK.01	Sink, room D205A	0.8	-	-	1
	042917.380A.D205BSK.01	Sink, room D205B	ND	-	-	1
	042917.380A.E104SK.01	Sink, room E104	ND	-	-	1
	042917.380A.E121SK.01	Sink, room E121	0.59	-	-	1
	042917.380A.E122SK.01	Sink, room E122	0.87	-	-	1
	042917.380A.E126DF.01	Drinking fountain, room E126	ND	-	-	1
	042917.380A.E127SK.01	Sink, room E127	1.2	-	-	1
	042917.380A.E150DF.01	Drinking fountain, hallway E150, NE corner, left side DF	ND	-	-	1
	042917.380A.E150DF.02	Drinking fountain, hallway E150, NE corner, right side DF	ND	-	-	1
042917.380A.E150DF.03	Drinking fountain, hallway E150, SE corner, left side DF	ND	-	-	1	
042917.380A.E150DF.04	Drinking fountain, hallway E150, SE corner, right side DF	ND	-	-	1	
042917.380A.F101SK.01	Sink, room F101, south side of west island	2.9	-	-	1	
042917.380A.F101SK.02	Sink, room F101, middle island, south side of room	1.6	-	-	1	
042917.380A.F101SK.03	Sink, room F101, SE corner	1.7	-	-	1	
042917.380A.F101SK.04	Sink, room F101, east island, south end	0.74	-	-	1	
042917.380A.F101SK.05	Sink, room F101, east island, north end	0.83	-	-	1	
042917.380A.F101SK.06	Sink, room F101, middle island, north side of room	2.7	-	-	1	

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Mountain Range HS

<u>Sample Type</u>	<u>Sample ID</u>	<u>Sample Description</u>	<u>Lead Result</u> <u>in</u> <u>PPB</u>	<u>Action Taken</u>	<u>Back in</u> <u>Service Date</u>	<u>Sample</u> <u>Count</u>
	042917.380A.F101SK.07	Sink, room F101, north wall, east side	0.83	-	-	1
	042917.380A.F101SK.08	Sink, room F101, NW corner	1.3	-	-	1
	042917.380A.F101SK.09	Sink, room F101, north side of west island	1.5	-	-	1
	042917.380A.F106DF.01	Drinking fountain, hallway F106, south wall, left side DF	ND	-	-	1
	042917.380A.F106DF.02	Drinking fountain, hallway F106, south wall, right side DF	ND	-	-	1
	042917.380A.F106DF.03	Drinking fountain, hallway F106, south wall, bottle fill static	ND	-	-	1
	042917.380A.F123DF.01	Drinking fountain, hallway F123, west wall, far left DF	ND	-	-	1
	042917.380A.F123DF.02	Drinking fountain, hallway F123, west wall, right of DF.01	ND	-	-	1
	042917.380A.F123DF.03	Drinking fountain, hallway F123, west wall, right of DF.02	ND	-	-	1
	042917.380A.F123DF.04	Drinking fountain, hallway F123, west wall, far right DF	ND	-	-	1
	042917.380A.F131SK.01	Sink, room F131	2	-	-	1
	042917.380A.F136DF.01	Drinking fountain, hallway F136, south wall, left side DF	ND	-	-	1
	042917.380A.F136DF.02	Drinking fountain, hallway F136, south wall, right side DF	ND	-	-	1
	042917.380A.G105DF.01	Drinking fountain, hallway G101, north wall, left side DF	ND	-	-	1
	042917.380A.G105DF.02	Drinking fountain, hallway G101, north wall, right side DF	ND	-	-	1
	042917.380A.G121SK.01	Sink, room G121	1.2	-	-	1
	042917.380A.H102DF.01	Drinking fountain, room H102 SW corner, DF not working	ND	-	-	1
	042917.380A.H102SK.01	Sink, room H102, NW corner	0.54	-	-	1
Initial Sample Total						76

Resultados de las Muestras de Agua

Guía en español para leer los resultados de las pruebas de las muestras de agua en su escuela

Por favor, consulte esta guía para entender mejor los resultados en español de las pruebas de las muestras de agua en su escuela:

Report Legend: Leyenda del Reporte

- Sample ID: Lab Generated Unique ID = ID de la Muestra: ID única creada por el laboratorio
- Yellow: 15-19.9PPB | Orange: 20 PPB and Above = Amarillo: 15-19.9 ppb | Anaranjado: 20 ppb y más
- PPB: partes por mil millones
- ND: No detectable (por debajo del límite detectable)

Sample Description: ID de la Muestra

- Drinking fountain = Fuente de agua
- Sink = Lavabo
- Room ## = salón ##
- Middle of room = a mitad del salón
- North wall = pared del norte
- NE corner = esquina al noreste
- SE corner = esquina al sureste
- NW corner = esquina al noroeste
- SW corner = esquina al suroeste
- Next to SK.## = al lado del SK.## (SK=lavabo/fregadero)
- Hallway = pasillo
- Main hallway = pasillo principal
- Long main hallway = Pasillo principal largo
- Short main hallway = Pasillo principal corto

Lead Result in PPB = Resultados de plomo en PPB

La Agencia de Protección Ambiental (EPA, por sus siglas en inglés) mide la cantidad de plomo en el agua en "partes por mil millones" o "ppb (por sus siglas en inglés)." Una parte por mil millones equivale a una gota de agua en 55,000 galones. Al igual que otros distritos escolares en Colorado que voluntariamente están conduciendo estas pruebas, Adams 12 Five Star Schools está siguiendo las normas de EPA para eliminar y remediar cualquier accesorio de plomería que tenga niveles de plomo de 15 ppb o más.

Action = Acción

Taken offline = Desconectado/a