

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Rocky Top MS

Sample Type	Sample ID	Sample Description	Lead Result	Action Taken	Back in	Sample
			in PPB		Service Date	
Initial Sample	032217.282A.200DF.01	Drinking fountain, corridor 200, west wall, middle, left side	ND	-	-	1
	032217.282A.200DF.02	Drinking fountain, corridor 200, west wall, middle, right side	ND	-	-	1
	032217.282A.200DF.03	Drinking fountain, corridor 200, west wall, north end, left side	ND	-	-	1
	032217.282A.200DF.04	Drinking fountain, corridor 200, west wall, north end, right side	ND	-	-	1
	032217.282A.300DF.01	Drinking fountain, corridor 300, west wall, left side DF	ND	-	-	1
	032217.282A.300DF.02	Drinking fountain, corridor 300, west wall, right side DF	ND	-	-	1
	032217.282A.300DF.03	Drinking fountain, corridor 300, west wall, bottle fill station	ND	-	-	1
	032217.282A.500DF.01	Drinking fountain, corridor 500, west wall, middle, left side	ND	-	-	1
	032217.282A.500DF.02	Drinking fountain, corridor 500, west wall, middle, right side	ND	-	-	1
	032217.282A.500DF.03	Drinking fountain, corridor 500, west wall, middle, bottle fill station	ND	-	-	1
	032217.282A.500DF.04	Drinking fountain, corridor 500, west wall, north end, right side	ND	-	-	1
	032217.282A.500DF.05	Drinking fountain, corridor 500, west wall, north end, right side	ND	-	-	1
	032217.282A.A106SK.01	Sink, room A106	1.9	-	-	1
	032217.282A.A107SK.01	Sink, room A107	0.73	-	-	1
	032217.282A.A206SK.01	Sink, room A206	ND	-	-	1
	032217.282A.A207SK.01	Sink, room A207	0.92	-	-	1
	032217.282A.B103SK.01	Sink, room B103, library resource room	220	Taken offline	-	1
	032217.282A.B107SK.01	Sink, room B107	0.54	-	-	1
	032217.282A.B109SK.01	Sink, room B109	0.55	-	-	1
	032217.282A.C106SK.01	Sink, room C106	0.51	-	-	1
	032217.282A.C107SK.01	Sink, room C107	0.5	-	-	1
	032217.282A.C200SK.01	Sink, room C200, SW corner	ND	-	-	1
	032217.282A.C200SK.02	Sink, room C200, SE corner	0.7	-	-	1
	032217.282A.C206SK.01	Sink, room C206	2.9	-	-	1
	032217.282A.C207SK.02	Sink, room C207	0.59	-	-	1
	032217.282A.D106SK.01	Sink, room D106	1.3	-	-	1
	032217.282A.D121DF.01	Drinking fountain, room D121, south wall	ND	-	-	1
	032217.282A.D121DF.02	Drinking fountain, room D121, south wall, bottle fill station	ND	-	-	1
	032217.282A.D121SK.01	Sink, room D121	ND	-	-	1
	032217.282A.D123SK.01	Sink, room D123	ND	-	-	1
	032217.282A.D139SK.01	Sink, room D139	ND	-	-	1
	032217.282A.D200SK.01	Sink, room D200, west wall, north end	ND	-	-	1
	032217.282A.D200SK.02	Sink, room D200, west wall, south end	0.55	-	-	1
	032217.282A.D204SK.01	Sink, room D204	3.3	-	-	1
	032217.282A.D208SK.01	Sink, room D208, east wall, south end	0.78	-	-	1
	032217.282A.D208SK.02	Sink, room D208, east wall, middle	1	-	-	1
	032217.282A.D208SK.03	Sink, room D208, east wall, north end	3.2	-	-	1
	032217.282A.D211SK.01	Sink, room D211, east wall	0.96	-	-	1
	032217.282A.D211SK.02	Sink, room D211, SE corner, currently an art classroom	20	Taken offline	-	1
	032217.282A.D212SK.01	Sink, room D212	0.51	-	-	1
	032217.282A.E100DF.01	Drinking fountain, room E100, north wall, west end, right side	ND	-	-	1
	032217.282A.E100DF.02	Drinking fountain, room E100, north wall, west end, left side	ND	-	-	1
	032217.282A.E100DF.03	Drinking fountain, room E100, north wall, east end	ND	-	-	1
	032217.282A.E106SK.01	Sink, room E106	2	-	-	1
	032217.282A.E107DF.01	Drinking fountain, room E107, SW corner, left side DF	ND	-	-	1
032217.282A.E107DF.02	Drinking fountain, room E107, SW corner, right side DF	0.54	-	-	1	
032217.282A.E112SK.01	Sink, room E112	2.4	-	-	1	
032217.282A.E113DF.01	Drinking fountain, room E113, east wall, left side DF	ND	-	-	1	
032217.282A.E113DF.02	Drinking fountain, room E113, east wall, right side DF	ND	-	-	1	
032217.282A.F104SK.01	Sink, room F104, NE corner	1.8	-	-	1	
032217.282A.F104SK.02	Sink, room F104, NW corner	0.59	-	-	1	
032217.282A.F104SK.03	Sink, room F104, west wall	1.4	-	-	1	
032217.282A.F104SK.04	Sink, room F104, SW corner	ND	-	-	1	
032217.282A.F104SK.05	Sink, room F104, south wall	1.6	-	-	1	
032217.282A.F104SK.06	Sink, room F104, SE corner	4.5	-	-	1	
032217.282A.F105SK.01	Sink, room F105	3.2	-	-	1	
032217.282A.F115DF.01	Drinking fountain, room F115	ND	-	-	1	
032217.282A.F122DF.01	Drinking fountain, room F122	ND	-	-	1	
032217.282A.F122SK.01	Sink, room F122	1.4	-	-	1	
Initial Sample Total						59

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above
 ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Rocky Top MS

<u>Sample Type</u>	<u>Sample ID</u>	<u>Sample Description</u>	<u>Lead Result</u> <u>in</u> <u>PPB</u>	<u>Action Taken</u>	<u>Back in</u> <u>Service Date</u>	<u>Sample</u> <u>Count</u>
Re-test Sample - 1	071217.282A.B103SK.01	Sink, room B103, library resource room	14	Back in service	7/12/2017	1
	071217.282A.D211SK.01	Sink, room D211, SE corner, currently an art classroom	12	Back in service	7/12/2017	1
Re-test Sample - 1 Total						2