

## Water Sampling Results

### Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above  
 ND: Non-detect (below detection limit) | PPB: Parts per Billion

**School Name**    **Silver Creek ES**

Sample Type	Sample ID	Sample Description	Lead Result	Action Taken	Back in Service	Sample Count
			in PPB		Date	
Initial Sample	030317.199A.A104SK.01	Sink, room A104	0.63	-	-	1
	030317.199A.A106SK.01	Sink, room A106	ND	-	-	1
	030317.199A.A110DF.01	Drinking fountain, room A110	ND	-	-	1
	030317.199A.A113DF.01	Drinking fountain, room A113, attached to sink	5.2	-	-	1
	030317.199A.A113SK.01	Sink, room A113	1.5	-	-	1
	030317.199A.A116SK.01	Sink, room A116	ND	-	-	1
	030317.199A.A117ADF.01	Drinking fountain, corridor A117A	ND	-	-	1
	030317.199A.A120DF.01	Drinking fountain, room A120, attached to sink	ND	-	-	1
	030317.199A.A120SK.01	Sink, room A120	1	-	-	1
	030317.199A.A126DF..01	Drinking fountain, room A120, attached to sink	ND	-	-	1
	030317.199A.A126SK.01	Sink, room A120	3	-	-	1
	030317.199A.A128DF.01	Drinking fountain, room A128, attached to sink	ND	-	-	1
	030317.199A.A128SK.01	Sink, room A128	0.82	-	-	1
	030317.199A.A129DF.01	Drinking fountain, room A129, attached to sink	ND	-	-	1
	030317.199A.A129SK.01	Sink, room A129	ND	-	-	1
	030317.199A.A133DF.01	Drinking fountain, corridor A133	ND	-	-	1
	030317.199A.A134DF.01	Drinking fountain, room A134, attached to sink	ND	-	-	1
	030317.199A.A134SK.01	Sink, room A134	0.78	-	-	1
	030317.199A.A135DF.01	Drinking fountain, room A135, attached to sink	ND	-	-	1
	030317.199A.A135SK.01	Sink, room A135	0.62	-	-	1
	030317.199A.A136DF.01	Drinking fountain, room A136, attached to sink	ND	-	-	1
	030317.199A.A136SK.01	Sink, room A136	0.51	-	-	1
	030317.199A.A138DF.01	Drinking fountain, room A138, attached to sink	ND	-	-	1
	030317.199A.A138SK.01	Sink, room A138	ND	-	-	1
	030317.199A.A139DF.01	Drinking fountain, room A139, attached to sink	ND	-	-	1
	030317.199A.A139SK.01	Sink, room A139	ND	-	-	1
	030317.199A.B100SK.01	Sink, room B100, middle of room, north side of wall	7.4	-	-	1
	030317.199A.B100SK.02	Sink, room B100, middle of room, south side of wall	0.5	-	-	1
	030317.199A.B100SK.03	Sink, room B100, middle of room, south end, west wall	1.1	-	-	1
	030317.199A.B100SK.04	Sink, room B100, middle of room, south wall of kitchen	19	Taken offline	-	1
	030317.199A.B114DF.01	Drinking fountain, room B114, attached to sink	ND	-	-	1
	030317.199A.B114SK.01	Sink, room B114, SE corner	ND	-	-	1
	030317.199A.B114SK.02	Sink, room B114, west wall, right side sink	0.54	-	-	1
	030317.199A.B114SK.03	Sink, room B114, west wall, left side sink	ND	-	-	1
	030317.199A.C100DF.01	Drinking fountain, room C100, attached to sink	ND	-	-	1
	030317.199A.C100SK.01	Sink, room C100	ND	-	-	1
	030317.199A.C102DF.01	Drinking fountain, room C102, attached to sink	ND	-	-	1
	030317.199A.C102SK.01	Sink, room C102	0.74	-	-	1
	030317.199A.C103DF.01	Drinking fountain, room C103, attached to sink	ND	-	-	1
	030317.199A.C103SK.01	Sink, room C103	0.59	-	-	1
	030317.199A.C104DF.01	Sink, corridor C104	ND	-	-	1
	030317.199A.C108DF.01	Drinking fountain, room C108, attached to sink	ND	-	-	1
	030317.199A.C108SK.01	Sink, room C108	0.79	-	-	1
	030317.199A.C109DF.01	Drinking fountain, room C109, attached to sink	ND	-	-	1
	030317.199A.C109SK.01	Sink, room C109	ND	-	-	1
	030317.199A.C110DF.01	Drinking fountain, room C110, attached to sink	ND	-	-	1
	030317.199A.C110SK.01	Sink, room C110	ND	-	-	1
	030317.199A.C112DF.01	Drinking fountain, room C112, attached to sink	ND	-	-	1
	030317.199A.C112SK.01	Sink, room C112	ND	-	-	1
	030317.199A.C113DF.01	Drinking fountain, room C113, attached to sink	ND	-	-	1
030317.199A.C113SK.01	Sink, room C113	ND	-	-	1	
030317.199A.D100DF.01	Drinking fountain, room D100, attached to sink	ND	-	-	1	
030317.199A.D100SK.01	Sink, room D100	ND	-	-	1	
030317.199A.D102DF.01	Drinking fountain, room D102, attached to sink	ND	-	-	1	
030317.199A.D102SK.01	Sink, room D102	ND	-	-	1	
030317.199A.D103DF.01	Drinking fountain, room D103, attached to sink	ND	-	-	1	
030317.199A.D103SK.01	Sink, room D103	ND	-	-	1	

## Water Sampling Results

### Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above  
 ND: Non-detect (below detection limit) | PPB: Parts per Billion

**School Name** Silver Creek ES

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
	030317.199A.D104DF.01	Sink, corridor D104	ND	-	-	1
	030317.199A.D108DF.01	Drinking fountain, room D108, attached to sink	ND	-	-	1
	030317.199A.D108SK.01	Sink, room D108	ND	-	-	1
	030317.199A.D109DF.01	Drinking fountain, room D109, attached to sink	ND	-	-	1
	030317.199A.D109SK.01	Sink, room D109	ND	-	-	1
	030317.199A.D110DF.01	Drinking fountain, room D110, attached to sink	ND	-	-	1
	030317.199A.D110SK.01	Sink, room D110	ND	-	-	1
	030317.199A.D112DF.01	Drinking fountain, room D112, attached to sink	ND	-	-	1
	030317.199A.D112SK.01	Sink, room D112	0.78	-	-	1
	030317.199A.D120DF.01	Drinking fountain, room D120, attached to sink	0.62	-	-	1
	030317.199A.D120SK.01	Sink, room D120	ND	-	-	1
	030317.199A.D125SK.01	Sink, room D125	ND	-	-	1
	030317.199A.D128SK.01	Sink, room D128	ND	-	-	1
	030317.199A.D131SK.01	Sink, room D131	ND	-	-	1
	030317.199A.D142DF.01	Drinking fountain, room D142, attached to SK.01	ND	-	-	1
	030317.199A.D142DF.02	Drinking fountain, room D142, attached to SK.02	ND	-	-	1
	030317.199A.D142SK.01	Sink, room D142, south wall, west side	0.89	-	-	1
	030317.199A.D142SK.02	Sink, room D142, south wall, east side	0.67	-	-	1
	030317.199A.D144DF.01	Drinking fountain, room D144, attached to SK.01	0.92	-	-	1
	030317.199A.D144DF.02	Drinking fountain, room D144, attached to SK.02	ND	-	-	1
	030317.199A.D144SK.01	Sink, room D144, south wall, east side	0.59	-	-	1
	030317.199A.D144SK.02	Sink, room D144, south wall, west side	0.57	-	-	1
<b>Initial Sample Total</b>						<b>79</b>
Retest Sample - 1	041217.199A.B100SK.04	Sink, room B100, middle of room, south wall of kitchen	2.9	Back in service	4/27/2017	1
<b>Retest Sample - 1 Total</b>						<b>1</b>