

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name **Stellar ES**

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	030717.190A.A112DF.01	Drinking fountain, room A112, east side, attached to sink	1.2	-	-	1
	030717.190A.A112DF.02	Drinking fountain, room A112, west side, attached to sink	0.56	-	-	1
	030717.190A.A112SK.01	Sink, room A112, east side	0.76	-	-	1
	030717.190A.A112SK.02	Sink, room A112, west side	0.74	-	-	1
	030717.190A.A112SK.03	Sink, room A112, middle	4.9	-	-	1
	030717.190A.A113DF.01	Drinking fountain, room A113, west side, attached to sink	ND	-	-	1
	030717.190A.A113DF.02	Drinking fountain, room A113, east side, attached to sink	ND	-	-	1
	030717.190A.A113SK.01	Sink, room A113, west side	ND	-	-	1
	030717.190A.A113SK.02	Sink, room A113, east side	0.76	-	-	1
	030717.190A.A113SK.03	Sink, room A113, middle	0.91	-	-	1
	030717.190A.A117SK.01	Sink, room A117	0.74	-	-	1
	030717.190A.A125DF.01	Drinking fountain, room A125, attached to sink	0.52	-	-	1
	030717.190A.A125SK.01	Sink, room A125	ND	-	-	1
	030717.190A.A127DF.01	Drinking fountain, room A127, attached to sink	ND	-	-	1
	030717.190A.A127SK.01	Sink, room A127	4.2	-	-	1
	030717.190A.A129DF.01	Drinking fountain, room A129, attached to sink	ND	-	-	1
	030717.190A.A129SK.01	Sink, room A129	0.8	-	-	1
	030717.190A.A130DF.01	Drinking fountain, room A130, attached to sink	ND	-	-	1
	030717.190A.A130SK.01	Sink, room A130	0.6	-	-	1
	030717.190A.A131DF.01	Drinking fountain, room A131, attached to sink	ND	-	-	1
	030717.190A.A131SK.01	Sink, room A131	0.93	-	-	1
	030717.190A.A132DF.01	Drinking fountain, room A132, attached to sink	0.86	-	-	1
	030717.190A.A132SK.01	Sink, room A132	0.5	-	-	1
	030717.190A.A134DF.01	Drinking fountain, room A134, attached to sink	0.6	-	-	1
	030717.190A.A134SK.01	Sink, room A134	0.69	-	-	1
	030717.190A.A136DF.01	Drinking fountain, room A136, attached to sink	0.62	-	-	1
	030717.190A.A136SK.01	Sink, room A136	0.5	-	-	1
	030717.190A.A202DF.01	Drinking fountain, room A202, attached to sink	ND	-	-	1
	030717.190A.A202SK.01	Sink, room A202	0.69	-	-	1
	030717.190A.A203DF.01	Drinking fountain, room A203, attached to sink	ND	-	-	1
	030717.190A.A203SK.01	Sink, room A203	0.64	-	-	1
	030717.190A.A214DF.01	Drinking fountain, room A214, attached to sink	ND	-	-	1
	030717.190A.A214SK.01	Sink, room A214	2.5	-	-	1
	030717.190A.A215DF.01	Drinking fountain, room A215, attached to sink	0.88	-	-	1
	030717.190A.A215SK.01	Sink, room A215	ND	-	-	1
	030717.190A.A225DF.01	Drinking fountain, room A225, attached to sink	0.53	-	-	1
	030717.190A.A225SK.01	Sink, room A225	0.58	-	-	1
	030717.190A.A226ADF.01	Drinking fountain, room A226A, attached to sink	ND	-	-	1
	030717.190A.A226ASK.01	Sink, room A226A	1.3	-	-	1
	030717.190A.A226BDF.01	Drinking fountain, room A226B, attached to sink	0.75	-	-	1
	030717.190A.A226BSK.01	Sink, room A226B	0.97	-	-	1
	030717.190A.A227DF.01	Drinking fountain, room A227, attached to sink	ND	-	-	1
	030717.190A.A227SK.01	Sink, room A227	ND	-	-	1
	030717.190A.A229DF.01	Drinking fountain, room A229, attached to sink	1	-	-	1
	030717.190A.A229SK.01	Sink, room A229	0.63	-	-	1
030717.190A.A230DF.01	Drinking fountain, room A230, attached to sink	ND	-	-	1	
030717.190A.A230SK.01	Sink, room A230	1.1	-	-	1	
030717.190A.A231DF.01	Drinking fountain, room A231, attached to sink	ND	-	-	1	
030717.190A.A231SK.01	Sink, room A231	0.86	-	-	1	
030717.190A.A232DF.01	Drinking fountain, room A232, attached to sink	0.59	-	-	1	
030717.190A.A232SK.01	Sink, room A232	0.79	-	-	1	
030717.190A.A234DF.01	Drinking fountain, room A234, attached to sink	0.74	-	-	1	
030717.190A.A234SK.01	Sink, room A234	0.69	-	-	1	
030717.190A.A236DF.01	Drinking fountain, room A236, attached to sink	0.97	-	-	1	
030717.190A.A236SK.01	Sink, room A236	ND	-	-	1	
030717.190A.B106DF.01	Drinking fountain, room B106, attached to sink	0.82	-	-	1	
030717.190A.B106SK.01	Sink, room B106	1.1	-	-	1	
030717.190A.B108SK.01	Sink, room B108	0.62	-	-	1	
030717.190A.B111SK.01	Sink, room B111	3	-	-	1	
030717.190A.B122SK.01	Sink, room B122	1.2	-	-	1	

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name **Stellar ES**

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	030717.190A.B135DF.01	Drinking fountain, room B135, attached to sink	1.2	-	-	1
	030717.190A.B135SK.01	Sink, room B135	ND	-	-	1
	030717.190A.B136SK.01	Sink, room B136	ND	-	-	1
	030717.190A.C100DF.01	Drinking fountain, corridor C100, SE wall, left side DF	ND	-	-	1
	030717.190A.C100DF.02	Drinking fountain, corridor C100, SE wall, right side DF	ND	-	-	1
	030717.190A.C102SK.01	Sink, room C102	0.7	-	-	1
	030717.190A.C102SK.02	Drinking fountain, room C102, attached to sink	0.7	-	-	1
	030717.190A.C105SK.01	Sink, room C105	1.1	-	-	1
	030717.190A.C107SK.01	Sink, room C107	4.1	-	-	1
	030717.190A.C115DF.01	Drinking fountain, room C115, NW corner, left side DF	ND	-	-	1
	030717.190A.C115DF.02	Drinking fountain, room C115, NW corner, right side DF	ND	-	-	1
	030717.190A.C117SK.01	Sink, room C117	0.62	-	-	1
	030717.190A.C123SK.01	Sink, room C123	2.2	-	-	1
	030717.190A.C145SK.01	Sink, room C145, north side	1.1	-	-	1
	030717.190A.C145SK.02	Sink, room C145, north side, middle of room	5.8	-	-	1
	030717.190A.C145SK.03	Sink, room C145, south side, middle of room	7.8	-	-	1
	030717.190A.C145SK.04	Sink, room C145, south side, kitchen	110	Taken offline	-	1
Initial Sample Total						77
Re-test Sample - 1	072117.190A.C145SK.04	Sink, room C145, south side, kitchen	2.9	Back in service	8/3/2017	1
Re-test Sample - 1 Total						1